



8-pin RJ-45

Pin	Signal	Mode	
01	TxD+/D+	Transmit Data Positive Data+	Output
02	TxD-/D-	Transmit Data Negative Data-	Output
03	RxD+	Receive Data Positive	Input
04	RxD-	Receive Data Negative	Input
05	RTS+	Request To Send Positive	Output
06	RTS-	Request To Send Negative	Output
07	CTS+	Clear To Send Positive	Input
08	CTS-	Clear To Send Negative	Input