



10-pin RJ-45

Pin	Signal	Mode	
01	GND	Ground	
02	TxD+/D+	Transmit Data Positive Data+	Output
03	TxD-/D-	Transmit Data Negative Data-	Output
04	RxD+	Receive Data Positive	Input
05	RxD-	Receive Data Negative	Input
06	RTS+	Request To Send Positive	Output
07	RTS-	Request To Send Negative	Output
08	CTS+	Clear To Send Positive	Input
09	CTS-	Clear To Send Negative	Input
10	GND	Ground	