

Digital Input/Counter	Readback as 0	Readback as 1
Wet Contact (Sink)	+10 ~ +50 Vdc	OPEN or <4 Vdc
Wet Contact (Source)	+10 ~ +50 Vdc	OPEN or <4 Vdc

Digital Input/Counter	ON State Readback as 1
Dry Contact	
	OFF State Readback as 0